

Appendix B: Condition of Existing Bridge

1. Failure of waterproofing due to lack of bond with deck concrete



2. Failure of previous repair due to continuing corrosion of reinforcement



3. Leakage through deck and ongoing deterioration of repaired areas



4. Leakage through deck and ongoing deterioration of reinforced concrete members